

Firmware Version Reference for Baseline Products

As of February 7, 2019

BaseStation 3200™					
	Firmware Version	Description	Compatibility	Update Path	Notes
	12.29 and earlier	Outdated Legacy versions	BaseManager FlowStation V1	Update first to V12.34	Cannot update directly to V16.6 from these versions
	12.30 – 12.34	Current Legacy versions	BaseManager FlowStation V1 SubStation V1	Update directly to V16.6	Controller must be on V16.6 before it can be updated to V17
	16.0 – 16.5	Initial V16 versions	AppManager BaseManager PipeView FlowStation V2 SubStation V1.2	Update directly to V16.6	Controller must be on V16.6 before it can be updated to V17
	16.6	Includes bug fixes and support for the automatic security updater	AppManager BaseManager PipeView FlowStation V2 SubStation V1.2	Update directly to V17.0 (optional) or continue on V16	Controller can remain on the V16 platform and will operate without the enhanced security functions. If controller remains on V16, make sure connected performance components are on compatible versions.
	17.0	Enhanced security features and the ability to have security updates automatically pushed to the controller without a firmware update	AppManager BaseManager PipeView FlowStation V3 SubStation V2		If connected, FlowStation must be updated to V3; SubStation must be updated to V2

Firmware Version Reference for Baseline Products

BaseStation 1000™					
	Firmware Version	Description	Compatibility	Update Path	Notes
	1.18 and earlier	<ul style="list-style-type: none"> • Supports 40 programs • Integrated web server 	BaseManager 3G Cell Modem	Update directly to V1.21	
	1.19	<ul style="list-style-type: none"> • Supports 40 programs • Integrated web server 	AppManager BaseManager 3G Cell Modem	Update directly to V1.21	
	1.21	<ul style="list-style-type: none"> • Enhanced security features • Supports 30 programs • No integrated web server 	AppManager BaseManager 3G Cell Modem 4G Cell Modem		Controller cannot have more than 30 programs You are no longer able to use the integrated web server; you need to use LiveView instead

Firmware Version Reference for Baseline Products

SubStation™					
	Firmware Version	Description	Compatibility	Update Path	Notes
	1.0	Initial release	BaseStation 3200 V12.30 – 12.34	Update directly to V2.0	If the connected BaseStation 3200 is staying on the V12 firmware, the SubStation must stay on V1.0
	1.2	Support for BaseStation 3200 V16 firmware	BaseStation 3200 V16.1 – 16.6	Update directly to V2.0	If the connected BaseStation 3200 is staying on the V16 firmware, the SubStation must stay on V1.2
	2.0	Enhanced security features	BaseStation 3200 V17		If the connected BaseStation 3200 is updated to the V17 firmware, the SubStation must be updated to V2.0

Firmware Version Reference for Baseline Products

FlowStation™					
	Firmware Version	Description	Compatibility	Update Path	Notes
	1.0	Initial release	BaseStation 3200 V12.29 and earlier V12.30 – 12.34	Update directly to V3.0	If the connected BaseStation 3200 is staying on the V12 firmware, the FlowStation must stay on V1.0
	2.0	<ul style="list-style-type: none"> • Support for the new Flow model • Support for PipeView and the FlowStation App 	BaseStation 3200 V16.1 – 16.6 PipeView FlowStation App	Update directly to V3.0	If the connected BaseStation 3200 is staying on the V16 firmware, the FlowStation must stay on V2.0
	3.0	Enhanced security features	BaseStation 3200 V17 PipeView FlowStation App		If the connected BaseStation 3200 is updated to the V17 firmware, the FlowStation must be updated to V3.0